

EPA/UIC INSPECTION REPORT

RECEIVED

JAN 18 1990

EPA 6
REGION VI

Inspection Type reg.
Inspection Frequency status
Violation Code _____

Inventory No. 2426
Authorization _____
Authorized to Inject _____

Company/Operator KWB
Business Address 3300 15 E. 5th St. #3300 Tulsa, OK 74103
Individual Contacted Pope Title _____
Lease Name & Well No. _____ #32
Legal Description 0340' F^NL 0125' F^EL NW/4 Sec. 17 T 23 R 12
Well Information: SWD/ER, Active/TA/P&A

Authorized Injection: Pressure _____ Rate _____
Long String Casing Size 6 5/8" 5.5 liner Tubing Size _____

Report of Conditions as of this Date:

Lease: Active/Inactive Well hooked up for injection: Yes No
Injecting at time of inspection: Yes No
Required fittings on tubing and casing/tubing annulus: Yes/No Not Applicable
Injection Pressure zero; How Determined P & H
Annular Pressure _____; How Determined ↓
Injection Rate ↓; How Determined ↓
Well plugged at Surface: Yes/No/Undetermined
Samples Taken no Photographs Taken none

Description of wellhead hookup and injection facility:

P & H, buried lines adjacent to area, reportedly for gas injection at one time, pit needs to be filled.

Weather Conditions and Observations high thin scattered, northwest winds at 8 mph, 44°F, location on east side of RR track.

Inspection Date 01/12/90 Time Arrived 1540 Departed 1550
Field Inspector Blair Edmonson
EPA Reviewer _____ Date _____